



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
September 14, 2006

Supervisor 100271

**Mine Name:** Lucky Boy Claims  
**Operator Name:** Interstate Gold and Gas

**Permit number:** S0030021  
**Inspection Date:** September 6, 2006  
**Time:** 3:30 pm

**Inspector(s):** Lynn Kunzler, DOGM  
**Other Participants:** none  
**Mine Status:** Inactive/reclaimed

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

To check status to for surety amount determination..

**Inspection Summary:**

1. This site has been inactive for almost ten years. Since the last inspection, it was noted that the access road had been reclaimed, by regrading and apparent seeding. Stumps, logs and rocks had been placed to prevent vehicle access. The road was dominated by desirable perennial vegetation, such as snowberry, sagebrush, rabbitbrush, serviceberry, fescue and Thickspike (?) wheatgrass. Vegetation cover exceeded the surrounding vegetation cover. While not much regrading had occurred at the mine site, vegetation had established over most of the site and exceeded the cover of the adjacent areas.

Photos were taken to document site conditions.

**Conclusions and Recommendations:**

1. Since this site has been inactive for nearly ten years, and vegetation is established (reclamation success standard is achieved), it is recommended that the Division close this file.

**Inspector's Signature**

LK:pb

O:\M003-BoxElder\S0030021-LuckyBoyClaims\inspections\Insp-09062006.doc

**Date:** Sept 14, 2006